5

10

15

- 24 -

## **ABSTRACT**

A tool selection method, for a machine tool, comprising the steps of identifying the maximum tip distance (D2) of a currently selected tool (141), a next designated tool (142) and an intermediate tool (143) disposed therebetween; moving a tool rest (10) in the +(plus)X-axis direction after a machining by the currently selected tool (141) is completed until the tip of the currently selected tool (141) is spaced from a workpiece (W) along the X-axis by a distance provided by adding a clearance distance (E) to a difference between the maximum tip distance (D2) and the tip distance (D3) of the currently selected tool (141); moving the tool rest (10) in the +(plus)Y-axis direction until the tip of the next designated tool (142) is aligned with the rotation center axis (12a) of the workpiece (W) in the Xaxis direction; and moving the tool rest (10) in the -(minus) X-axis direction.